

1993

OSCODA COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in COMMISSION

Oscoda (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>28N</u> R <u>1E</u>	<u>A-6</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

Liber 3 Pg. 155

FILED
 At 12:02 o'clock P M
 Date 12-6 19 93
 Clerk/Register of Deeds
 Register of Deeds Stamp & File Number

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

I, Marvin E. Myers, in a field survey on Nov 16, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

L.1, pg.271 DNR 1982 P.S. 10068 Walker Survey Feb. 1992
 Mon. - DNR Mon. Mon. - DNR Mon.
 WIT: 2" R.Pine S35°E 51.25'
 2" R.Pine N31°E 21.18'
 E½ Sec. 13, T28N, RLW North 69.70'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found DNR Std. pipe with aluminum cap verified location by measurement to accessories and corners of records and is accepted as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon. - Left in place Std. DNR Mon.
 WIT: PK nail in NW side of 10" Red Pine (Norway) N33°E 21.48
 PK nail in S. side of 6" Red Pine(Norway) N60°E 35.02
 PK nail in W. side of 9" Red Pine (Norway) S33°E 51.18
 PK nail in S. Side of 7" Poplar S79°W 25.23



Signed by Marvin E. Myers Date Dec 6, 1993
 Surveyor's Michigan License No. 31600
 Date approved Oct 25, 1993 Oscoda County Peer Group