

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

1993

Liber 3 Pg 157

For corners in

Oscoda OSCODA Located In: \_\_\_\_\_ Corner Code # \_\_\_\_\_  
(County)

1. Public Land Survey	T <u>28N</u> R <u>1E</u>	A-8
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

**FILED**  
At 12:04 o'clock PM  
Date 12-6 19 93

Clerk/Register of Deeds  
Register of Deeds Stamp & File Number

- 4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
- 5. Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Marvin E. Myers, in a field survey on NOV 17, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:  
This corner was not set in original GLO survey

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
Found 1 1/2" Pipe (typical Schaaf Monument). Verified position by measurement to corners of record; and is accepted as the best evidence of the position of the original corner. Replaced monument with Std. Oscoda County Monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- Mon. - Std. Oscoda County Mon.
- WIT: P.K. S. 8" Maple N74°E 7.27'
- P.K. E. 5" Maple S20°E 24.68'
- P.K. NE 5" Maple S41°W 16.30'
- P.K. SW 17" Oak N51°W 17.67'



Signed by Marvin E. Myers Date Dec 6, 1993

Surveyor's Michigan License No. 31600