Montmorency County Remonumentation

LAND CORNER RECORDATION CERTIFICATE For corners in Filing Requirement of Act 74, Mich. P.A. 1970 L3 pg Oscoda Located In: Corner Code ≠# (County) FILED T 28N R 1E At 8: 40 o'clock A M Date Doc. 14 19 93 1. Public Land Survey K-3 T_28N R_1E - K-4 T _____ R ____ __ R _ 2. Property Controlling _ T ____ R ____ Clerk/Register of Doods in Section ___ T ___ R ___ Occedi County, Michigan Register of Deeds Stamp & File Number 3. Miscellaneous ___ T ___ R ____ Property in Sec. ___ Recorded Plat _ 5 Private Claims Donald E. Marlatt in a field survey on December 9 ... , 19 ___93 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: (K-3) Sec. Cor. Comm. to 1-2-11 & 12. (K-4) 4 Cor. Comm. to Sec's 11 & 12. Original Cor. set by W.R. Coon Dec. 1839. Original Cor. set by W.R. Coon Dec. 1839. Spruce Pine 7-N13E-29 Spruce Pine 4-N45W-4 Spruce Pine 6-S13W-16 Spruce Pine 6-S45E-7 Cor. Est. by Seeley 1915. Cor. set by Seeley 1915. Survey by Caldwell for Stick Fort June 196 Act 74 by G. McKelvey L. 1, P. 21 Survey by Caldwell for Stick Fort 4-28-1975. Survey by Caldwell for Stick Fort Enter-Survey by D.E. Marlatt L. 4, P. 476. Survey by D.E. Marlatt 7-14-1989. prises 1967. Recorded Plat Woodland Manor. Survey by G. McKelvey L. 1, P. 295. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (K-3) Sec. Cor. Comm. to 1-2-11 & 12. Fnd. 3/4" bar buried 15" ¼ Cor. Comm. to Sec's 11 & 12. (K-4) Fnd. 1" Pinched Pipe. in Tel. wires. Plat Mon. 33' East. West side on road. No evidence of original Corner. Note: Previous Co. Surveyors have indicated that the original Twp. notes are fraudulent. Peer Group approved as a careful and faithful establishment of the position of the corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Sec. Cor. Comm. to 1-2-11 & 12. 3/4" bar. (K-4) 1/4 Cor. Comm. to Sec's 11 & 12. Set Co. Mon. S 75° W 14" J. Pine 82.28' N 40° E 12" J. Pine 68.78' N 37° W 11" J. Pine 86.10' N 47° E 8" Oak 68.93' S 52° E 14" J. Pine 50.84' East Plat Conc. Mon. 33.0' S 35° E 12" J. Pine 52.71 S 85° W 6" Oak 45.33' SONALDE DONALD E. MARLATT Note: Witnesses marked with 30 penny spikes & I.D. tag #18660. SURVEYOR NO. Signed by Norvald E Marlatt Date 12-13-1993 18660

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND'SURVEYORS JAN.

Surveyor's Michigan License No. <u>18660</u>