

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY  
T 28 N R 2 E

DESCRIPTION OF CORNER 1/4 corner common to sections 8 & 17

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 12-15-70

WITNESSES TO CORNER..... P. Fole N 87 E 85.5'



10" J. Pine N 16 W 81.4'

7" J. Pine S 16 W 28.3'

AND (All Norm Caldwell Witnesses)

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found (1 1/4" Pipe) during a retracement survey of T28N-R2E.  
Used in previous local surveys for subdivision of Section 17. Best available  
evidence.

SURVEYOR'S SEAL

SIGNED

*Quintin H. Heston*  
REGISTERED LAND SURVEYOR 10068

DATE

12-22-70

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68