

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 E

DESCRIPTION OF CORNER Sec. corner common to Sections 7-8-17-18

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 12-15-70

WITNESSES TO CORNER..... 10" J. Pine S 60 W 19.7'



12" J. Pine S 07 W 44.3'

16" Oak S 56 E 53.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found (cable shaft) during a retracement survey of T28N-R2E.
Corner of long standing, having been used in local surveys by Henning, Caldwell,
Slattery and Smith.

SURVEYOR'S SEAL

SIGNED Quintin H. Collins DATE _____
REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing