


STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

OSCODA COUNTY
T 28 N R 2 E

DESCRIPTION OF CORNER 1/4 corner common to Sections 17 & 18
 CORNER MONUMENT Set Department Monument
 DATE MONUMENT PLACED AND WITNESSED 12-15-70
 WITNESSES TO CORNER.....



<u>8" J. Pine</u>	<u>N 22 W</u>	<u>21.3'</u>
<u>8" J. Pine</u>	<u>S 21 E</u>	<u>10.05'</u>
<u>7" J. Pine</u>	<u>N 65 E</u>	<u>16.3'</u>

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement survey, as established in 1934 Schaaf Survey. Replaced 1 1/2" pipe in concrete block with Department monument. Corner used in local surveys for subdivision of Sec. 17.

SURVEYOR'S SEAL

SIGNED *Leanneth A. Kelly* DATE 12-22-70
 REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse
 Area Forester (Regions I & II)
 District or Region Surveyor
 Forestry Div., Lansing