## STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**

## LAND CORNER RECORD

MONTMORENCY Oscoda

COUNTY

		T 28 6 29	R 1 8 2 E
DESCRIPTION OF CORNER _	TWP. Corner common	to Sections 1-6-31-36	
CORNER MONUMENT	Set Dept. Monument	•	
DATE MONUMENT PLACED AND	WITNESSED	11-25-70	· · · · · · · · · · · · · · · · · · ·
ITNESSES TO CORNER	5" N. Pine	N 80 E	31,41
N	2" N. Pine	N 70 W	65.21
	8" J. Pine	8 32 E	75.5'
	AND 6" Omk	S 40 W	42.7'
CIRCLE CORNER REGISTER		rell Witnesses	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced (found) pipe with Department Monument.

SURVEYOR'S SEAL

REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing