


STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

OSCODA COUNTY  
T 28 N R 1 & 2 E

DESCRIPTION OF CORNER N 1/16 corner common to Sections 18 and 13  
CORNER MONUMENT Set 1 1/2" pipe / concrete block.  
DATE MONUMENT PLACED AND WITNESSED 11-25-70  
WITNESSES TO CORNER.....



6" J. Pine S 80 W 27.2'  
11" J. Pine N 74 W 40.4'  
AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set midpoint and on line between the section corner North and 1/4 corner South.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED *Kimberly J. Dilling* DATE 11-27-70  
REGISTERED LAND SURVEYOR #10068

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68