STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES

L'AND CORNER RECORD

		OSCODA	COUNTY
		T 28 N	R 182E
DESCRIPTION OF CORNER _	Sec. corner common to Section		
	Left Oseoda County monument	in place	
CORNER MONUMENT Found. DATE MONUMENT PLASED AND			
WITNESSES TO CORNER	•		
3.0	Concrete Honument Ea	st	33.0'
	AND		
CIRCLE CORNER REGISTE	RED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This cerner was previously perpetuated by County Surveyor. Witnessed for our record.

SURVEYOR'S SEAL

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing