

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 E

DESCRIPTION OF CORNER N 1/16 corner common to Sections 9 & 10

CORNER MONUMENT Set 1 3/4" x 18" Pipe

DATE MONUMENT PLACED AND WITNESSED 12-7-70

WITNESSES TO CORNER.....



6" Oak N 15 E 15.6'

5" Oak S 58 E 27.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set midpoint, on line, between 1/4 corner and Section corner, to mark state land boundary.

SURVEYOR'S SEAL

SIGNED Connelly H. Estling DATE 12-10-70
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing