

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 E

DESCRIPTION OF CORNER Sec. corner common to Sections 4 & 5 on N. Twp boundary

CORNER MONUMENT Set Std. Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 12-15-70

WITNESSES TO CORNER..... 7" Oak S 10 W 54.1'



13" Oak S 55 E 13.5'

5" Oak S 25 E 6.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during survey in T28N-R2E. Found post bottom at proper departure for closing corner. Adjusted latitude slightly to conform to the standard township line.

SURVEYOR'S SEAL

SIGNED *County Register* DATE 12-22-70
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68