

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES  
LAND CORNER RECORD


OSCODA COUNTY  
T 28 N R 2 & 3 E

DESCRIPTION OF CORNER 1/4 corner common to Sections 7 & 12

CORNER MONUMENT Set Dept. Mon.

DATE MONUMENT PLACED AND WITNESSED 5-26-71

WITNESSES TO CORNER.....



8" Maple S 43 W 11.8'

5" Maple S 58 E 15.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set as being M.P.O.L. between the Section corners N & S by M. Schaaf in the Mid-1930s. We replaced his pipe in block of concrete with a Dept. Monument.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

*Thomas J. Ostling*  
REGISTERED LAND SURVEYOR

DATE

6-2-71

10068

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68