

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 E

DESCRIPTION OF CORNER Sec. corner common to Sections 11-12-13-14

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 5-25-71

WITNESSES TO CORNER..... 7" Cedar N 6 W 47.3'



10" Oak S 79 W 22.9'

16" Oak S 26 E 46.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by E. Houghton in Mid-1930s. He describes it as Randall's corner. Accepted by M. Schaaf who set pipe in block of concrete. We replaced this pipe with Dept. Monument.

SURVEYOR'S SEAL

SIGNED

Evanth Houghton
REGISTERED LAND SURVEYOR

DATE

6-1-71

DISTRIBUTION:

10068

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68