

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 E

DESCRIPTION OF CORNER E 1/16 Corner common to Secs. 12-13

CORNER MONUMENT Set 1" pipe 2' long

DATE MONUMENT PLACED AND WITNESSED 5-26-71

WITNESSES TO CORNER..... 7" Maple S 28 W 12.5'



7" Maple N 3 E 28.7'

9" Beech S 40 E 19.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set M.P.O.L. between the N-1/4 corner and the NE Section corner of Section 13.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Quail Pettig
REGISTERED LAND SURVEYOR

DATE

6-2-71

10068

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68