

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY  
T 28 N R 2 E

DESCRIPTION OF CORNER 1/4 corner common to Sections 12 - 13

CORNER MONUMENT Set Department Monument

DATE MONUMENT PLACED AND WITNESSED 5-25-71

WITNESSES TO CORNER..... \* 7" Maple N 38 E 51.8'



12" Maple N 35 W 47.55'

Steel Fence Post South 14.6'

AND \* Caldwell NBT  
Redtop Post North 33'

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by N. Caldwell (Rerod & plastic cap) in 1970, from our line and measurement. We replaced his point with a Dept. Mon.

SURVEYOR'S SEAL

SIGNED

*Annaly Ostling*

DATE

6-1-71

DISTRIBUTION:

REGISTERED LAND SURVEYOR 10068

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68