

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 & 3 E

DESCRIPTION OF CORNER 1/4 corner common to Sections 13 and 18

CORNER MONUMENT Set Dept. Mon.

DATE MONUMENT PLACED AND WITNESSED 5-25-71

WITNESSES TO CORNER..... 7" Maple (in clump) N 10 W 29.95'



22" Maple N 47 E 71.45'

3/4" Pipe & red top post West 33'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was probably set by G. Henning. MSHD found a 3/4" pipe 33' East of fence corner around 1960. N. Caldwell raised this with rerod and plastic cap in 1970. We replaced the pipe and rod with cap with a Dept. Monument.

SURVEYOR'S SEAL

SIGNED

Walter J. Ostling
REGISTERED LAND SURVEYOR

DATE

6-1-71

DISTRIBUTION:

10068

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68