

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 & 3 E

DESCRIPTION OF CORNER Sec. corner common to Sections 12-13-7-18

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 5-20-71

WITNESSES TO CORNER.....



21" B. Walnut S 42 W 40.8'

14" B. Walnut S 16 E 56.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was noted as old post in crossroads by E. Houghton (CCC). Schaaf replaced stake with pipe in block of concrete. Found and rewitnessed by MSHD around 1960. We replaced Schaaf pipe with Dept. Mon.

SURVEYOR'S SEAL

SIGNED *Terence Houghton* DATE 5-27-71
REGISTERED LAND SURVEYOR

#10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68