STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES



LAND CORNER RECORD

		OSCODA	COUNTY
		T <u>28 N</u>	R _ 2 & 3 E
DESCRIPTION OF CORNER	N 1/16 corner common	n to Sections 7 & 12	
CORNER MONUMENT	Set 1" pipe 2' long	·	
DATE MONUMENT PLACED AN	D WITNESSED5-26-	-71	
WITNESSES TO CORNER			
N	17" R. Pine	N 63 W	23.91
12	<u>15" R. Oak</u> AND	N 72 E	19.11
CIRCLE CORNER REGISTE	-		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set M.P.O.L. between the E 1/4 corner and the NE Section corner of Section 12.

SURVEYOR'S SEAL

SIGNED

Cay Colling DATE 6-2-7

DISTRIBUTION:

REGISTERED LAND SURVEYOR TOOKS

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing