## STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES



## LAND CORNER RECORD

		OSCODA	COUNTY
		Ť <u>28</u>	<u>N</u> R <u>2 E</u>
DESCRIPTION OF CORNER	k Corner on N.	Bdy Section 3	<u>-</u>
CORNER MONUMENT	Set Dept. Mon.		
DATE MONUMENT PLACED AND W	ITNESSED 6-10-	-71	
WITNESSES TO CORNER			
N	5" R. Oak	S 14	E 12.0'
3	4" Maple	S 43	<u> </u>
	AND		
CIDCLE CORNER REGISTERE	D		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set M.P.O.L. between the N.E. and N.W. section corners of Section 3.

SURVEYOR'S SEAL

DISTRIBUTION:

10068

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68