

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

OSCODA COUNTY


T 28 N R 2 E

DESCRIPTION OF CORNER E. 1/16 cor. on North Line - Sec. 2

CORNER MONUMENT Set 1" X 24" Pipe

DATE MONUMENT PLACED AND WITNESSED 6-10-71

WITNESSES TO CORNER.....



12" Oak S 40 E 45.7'

10" Elm S 10 W 26.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set M.P.O.L. between the N $\frac{1}{4}$ cor. and the N.E. section corner of Section 2.

SURVEYOR'S SEAL

SIGNED *Timothy J. Ostling* DATE 6-17-71
REGISTERED LAND SURVEYOR

DISTRIBUTION:

10068

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68