

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

OSCODA COUNTY


T 28 N R 2 E

DESCRIPTION OF CORNER E 1/4 corner, Sec. 11

CORNER MONUMENT Set DNR Monument

DATE MONUMENT PLACED AND WITNESSED 7-15-71

WITNESSES TO CORNER.....



8" Maple N 53 W 9.2'

10" Maple N 06 W 13.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Previously restored by Marcus Schaaf, R.L.S. in mid 1930s from site of one U.S.B.T.

Replaced pipe and concrete block with DNR monument.



SURVEYOR'S SEAL

SIGNED

Kenneth J. Ostling
REGISTERED LAND SURVEYOR 10068

DATE

7-22-71

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68