STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		OSCODA	COUNTY
		T <u>28 N</u>	R <u>2</u> E
DESCRIPTION OF CORNER	E 1/16 on North li	ne, Section 12	
CORNER MONUMENT	Set 1"x24" pipe		
DATE MONUMENT PLACED AND W	· · · · · · · · · · · · · · · · · · ·	4-71	
N O O O O O O O O O O O O O O O O O O O	15" W. Pine	N 61 W	77.01
12	14" R. Oak AND	₩ со и	28.31
CIRCLE CORNER REGISTERE	D		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Set by standard survey procedure for the subdivision of sections.

REGISTANT	KENNETH J. OSTLING LAND SURVEYOR NO. 10068	GPN * OUT
4111	LAND SURVE	iiii

SURVEYOR'S SEAL

DISTRIBUTION: SIGNE

D Leweth DellingATE 7-21-71
REGISTERED LAND SURVEYOR

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing