## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

	OSCODA	COUNTY
	T <u>28 N</u>	R <u>2</u> E
DESCRIPTION OF CORNER NE corner, Section 10		
CORNER MONUMENT Set DNR Monument		
DATE MONUMENT PLACED AND WITNESSED		
WITNESSES TO CORNER		
N 8" Maple	_S 88 W	31.6
7" Maple	<del></del>	<del>6.51-</del>
AND		
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Previously established by C. O. Seeley, about 1917.

Recovered Seeley corner and replaced his pipe with DNR Monument.

KENNETH
J. OSTLING
LAND
SURVEYOR
NO.
10068
SURVEYOR'S SEAL

SIGNED REGISTERED LAND SURVEYOR #10068

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing