STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES

LAND CORNER RECORD

			OSCODA		COUNTY		
		T	281	N	R_	2	<u>E</u>
DESCRIPTION OF CORNER	N 1/4 cormer, Section 12						
CORNER MONUMENT	Set Dept. Monument -						
DATE MONUMENT PLACED AND WIT	TNESSED						
WITNESSES TO CORNER				_			
N -	7" Maple		N_2_I	Ē		3	8.81
12]4" R. Qak		<u> </u>	i		4	5.01
A	ND						
CIRCLE CORNER REGISTERED	HOW CORNER WAS LOCATED AND	I DE	NTIFIED OR	R R	EST	ORED	•

Previously established by M. Schaaf by proportionate measurement.

Replaced pipe in concrete monument with D.N.R. monument at M.P.O.L. between section corners.

J. OSTL.
LAND
SURVEYOR
NO.
10068
LAND SURVEYOR
YOR'S SE/

SIGNED REGISTERED LAND SURVEYOR 20068

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing