

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY  
T 28 N R 2 E

DESCRIPTION OF CORNER E 1/4 corner, Section 2

CORNER MONUMENT Set DNR Monument

DATE MONUMENT PLACED AND WITNESSED 7-14-71

WITNESSES TO CORNER..... 7" Cedar S 30 E 22.0'



6" Cedar S 50 W 16.5'

30" W. Pine stp N 12 E 8.3'

AND

28" W. Pine stp N 53 E 11.2'

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Previously established by M. Schaaf by proportionate measurement.

Replaced Schaaf pipe with DNR monument, adjusted slightly for proper proportionate measurement.



SURVEYOR'S SEAL

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

SIGNED Kenneth Ostling DATE 7-21-71  
REGISTERED LAND SURVEYOR  
#10068