

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY  
T 28 N R 2 E

DESCRIPTION OF CORNER N. E. Corner, Section 15

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 11-22-71

WITNESSES TO CORNER..... \* 20" R.P. stp. N 42 W 10.1'



6" Bl. Oak N 28 W 25.2'

5" R. Pine N 11 E 55.8'

AND

\* Seeley NBT

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1-1/4" Pipe set by County Surveyor Seeley. Both Seeley NBTs in place.



SURVEYOR'S SEAL

SIGNED Kenneth J. Ostling DATE 11-29-71  
REGISTERED LAND SURVEYOR #10068

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68