

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY  
T 28 N R 2 E

DESCRIPTION OF CORNER N 1/8 corner common to sections 23-24

CORNER MONUMENT Set 1 1/2" x 16" pipe

DATE MONUMENT PLACED AND WITNESSED 12-22-69

WITNESSES TO CORNER.....



BT 7" W. Pine N 70 W 3.8'

BT 8" Aspen N 7 E 13.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by survey procedure during a retracement in this township.

Set to mark state property boundary.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

*Timothy J. Osting*  
REGISTERED LAND SURVEYOR #10068

DATE

12-29-69

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68