

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

OSCODA COUNTY


T	<u>28</u>	N	R	<u>2</u>	E
T	<u>28</u>	N	R	<u>3</u>	E

DESCRIPTION OF CORNER Sec. corner common to Sections 13-24-18-19

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 12-23-69

WITNESSES TO CORNER..... _____



12" R. Pine S 50 W 35.9'

11" Tw. Oak S 45 E 52.6'

AND

22" Cr. Oak N 75 E 36.2'

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner found during a retracement in this area. Original restored by Seeley from U.S.B.T. and found acceptable by subsequent surveys. Probably an original corner restoration.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Levitt J. Bell
REGISTERED LAND SURVEYOR #10068

DATE

12-29-69

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing