

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

OSCODA COUNTY


T 28 N R 2 E
T 28 N R 3 E

DESCRIPTION OF CORNER 1/4 corner common to Sections 24 - 19

CORNER MONUMENT Drove 1/2 x 14" iron bar.

DATE MONUMENT PLACED AND WITNESSED 12-23-69

WITNESSES TO CORNER..... 6" J. Pine S 10 W 144.2'



9" J. Pine N 48 W 84.4'

Center N-S road East 10'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner restored by proportionate measurement, midpoint on line between section corners. Nothing else located.

SURVEYOR'S SEAL

SIGNED

Levinth J. Osting

DATE

12-29-69

DISTRIBUTION:

REGISTERED LAND SURVEYOR #10068

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68