STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		OSCODA	COUNTY
		T <u>28 N</u>	R <u>2 E</u>
DESCRIPTION OF CORNER	N 1/8 corner common to Secti	ons 32 - 33	
CORNER MONUMENT	Set 1-1/2" x 16" pěpe		
NATE MONUMENT PLACED A	ND WITNESSED <u>5-13-69</u>		
ITNESSES TO CORNER	•••	-	
N	BT 8" J. Pine	S 07 E	15.2'
32	BT 5" J. Pine	S 55 E	21.0'
	AND 2" Thinwall pipe	West	34.0'
CIRCLE CORNER REGIST			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner set by standard survey procedure during a survey in this area.

Set corner to mark state land boundary.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED LICILLY DELLAR DATE
REGISTERED LAND SURVEYOR #10068

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing