

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 E

DESCRIPTION OF CORNER N 1/8 corner common to Sections 19 - 20

CORNER MONUMENT Set 1-1/2" pipe with concrete base

DATE MONUMENT PLACED AND WITNESSED 5-13-69

WITNESSES TO CORNER..... BT 15" Oak N 25 W 68.4'



Stone Pile N 55 W 25'

NW Cor. of House N 74 E 600'±

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner set by standard survey procedure during a retracement in this area.

Set corner to mark state land boundary.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED *Timothy J. Oetting* DATE 5-20-69
REGISTERED LAND SURVEYOR #10068

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68