STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

	OSCODA	COUNTY
	T <u>28 N</u>	R <u>2 E</u>
DESCRIPTION OF CORNER <u>Sec. corner common to Sect</u>	ions 16-17-20-21	
CORNER MONUMENT Left 1-1/2" pipe in place		
DATE MONUMENT PLACED AND WITNESSED 12-23-69		
WITNESSES TO CORNER * 14" Y Pine stp	N 07 E	42.1'
* 18" Y.Pine stp	N 55 W	162.4'
* 14" J. Pine	S 07 W	112.1'
AND N.C. Caldwell W	itnesses	
CIRCLE CORNER REGISTERED		

THIS CORNER WAS RECOVERED DURING A RETRACEMENT IN THIS TOWNSHIP. FOUND 1-1/2" PIPE AT CORNER WHICH MARKS POSITION ESTABLISHED BY C.O. SEELEY IN 1916 SURVEY. CORNER USED BY HENNING IN 1933, AND PERPETUATED BY N.C. CALDWELL IN 1963. THIS CORNER APPEARS SOMEWHAT OUT OF POSITION WITH REGARD TO E-W MEASUREMENT TO ADJACENT CORNERS. HOWEVER, IN VIEW OF ITS LONG STANDING, ITS CONTROL FOR ADJACENT OCCUPATION, ITS USE BY TWO OR MORE SUBSEQUENT SURVEYS, AND ITS GENERAL ACCEPTANCE, THIS POSITION MUST BE HONORED AS THE MOST ACCEPTABLE LOCATION FOR THIS CORNER.

SURVEYOR'S SEAL

SIGNED

DATE

12-29-69

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing