

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 E

DESCRIPTION OF CORNER 1/4 Corner common to Sections 16 - 21

CORNER MONUMENT Left R.R. spike in place

DATE MONUMENT PLACED AND WITNESSED 12-23-69

WITNESSES TO CORNER..... * 16" Y. Pine stp N 65 W 29.0'



* 4" R. Pine S 45 E 30.2'

N. C. Caldwell Witnesses

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement in this township. Found R.R. spike at corner as restored by N. C. Caldwell in recent survey. Previously established by C. O. Seeley in 1916 survey, and used by Henning in 1933 to partition Section 16. Acceptably located for proportionate measurement, using Seeley's section corners.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED *County Wetling* DATE 12-30-69
REGISTERED LAND SURVEYOR #10068

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68