

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY  
T 28 N R 2 E

DESCRIPTION OF CORNER Sec. corner common to Sections 13-14-23-24

CORNER MONUMENT Left 3/4" iron bar in place

DATE MONUMENT PLACED AND WITNESSED 12-23-69

WITNESSES TO CORNER..... P. Pole N 10 W 38.6'



6" Oak S 20 W 33.8'

8" Poplar S 25 E 31.2'

AND All N.C. Caldwell Witnesses

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement in this township. This corner perpetuated in 1966 survey by N. C. Caldwell, probably a restoration of 1916 Seeley corner. This corner previously used to subdivide Section 13, and our survey considers it acceptably located according to Seeley's record.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED *Kenneth A. Gelling* DATE 12-30-69  
REGISTERED LAND SURVEYOR #10068

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68