

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

OSCODA COUNTY


T 28 N R 2 E

DESCRIPTION OF CORNER 1/4 Corner common to Sections 9 - 16

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 11-5-69

WITNESSES TO CORNER.....



4" R. Pine N 6 W 33.6'

8" J. Pine N 82 E 24.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement in this township. Found G. D. Henning's post bottom as established in 1933 survey. This corner apparently used in locating a number of parcels in Sec. 16, and believe used in 1948 survey by F. Smith. Fits reasonably with section corners East and West.

SURVEYOR'S SEAL

SIGNED

*G. D. Henning*  
REGISTERED LAND SURVEYOR 10068

DATE

11-12-69

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68