

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 E

DESCRIPTION OF CORNER 1/4 Corner on S. Side Sec. 35

CORNER MONUMENT Set Dept. Mon. below surface

DATE MONUMENT PLACED AND WITNESSED 12-10-69

WITNESSES TO CORNER..... * 20" W. Pine Stp. N 40 W 56.4'



OBT 20" W. Pine Stp. N 35 E 13.1'

6" W. Pine N 28 E 43.4'

AND * Old NBT

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement in this area. Found 1½" pipe as established in 1935 Schaaf survey from U.S.B.T., which is still in place. Good original corner.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED *Clayton Ostling* DATE 12-10-69
REGISTERED LAND SURVEYOR #10068

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68