

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

OSCODA COUNTY


T 28 N R 2 E
T 28 N R 3 E

DESCRIPTION OF CORNER Sec. corner common to sections 25-36-30-31

CORNER MONUMENT Left 1½" pipe in place

DATE MONUMENT PLACED AND WITNESSED 12-10-69

WITNESSES TO CORNER..... 6" R. Pine S 80 E 53.5'



24" R. Pine N 58 W 9.8'

Center Road EAST 4.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement in this area. Found 1½" pipe apparently as established in Schaaf survey, and accepted and used in subsequent surveys.

Considered acceptable, as best evidence of corner.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED *Ernest Ostling* DATE 12-10-69
REGISTERED LAND SURVEYOR #10068

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68