

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 E

DESCRIPTION OF CORNER 1/4 Corner common to Sections 25 - 36

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 12-22-69

WITNESSES TO CORNER.....



16" R. Pine S 24 W 146.2'

4" J. Pine N 25 W 10.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was set during a retracement in this township. Set corner by proportionate measurement between section corners. No U.S. evidence. Schaaf pipe removed.

SURVEYOR'S SEAL

SIGNED

Wm. J. Ostling
REGISTERED LAND SURVEYOR #10068

DATE

12-28-69

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68