

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

OSCODA COUNTY


T 28 N R 2 E
T 28 N R 3 E

DESCRIPTION OF CORNER 1/4 Corner common to Sections 36 - 31

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 12-10-69

WITNESSES TO CORNER..... 15" J. Pine N 25 W 27.4'



12" J. Pine N 87 W 33.8'

13" J. Pine S 29 E 13.6'

AND

28" R. Pine N 86 E 75.8'

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey in T28-2E. Corner previously recovered in previous surveys by Seeley, Schaaf, and MSHD. Corner falls about 20' West of center of road.

SURVEYOR'S SEAL

SIGNED *Anneth J. Ketting* DATE 12-15-69
REGISTERED LAND SURVEYOR #10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68