

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

OSCODA COUNTY


T 28 N R 2 E

DESCRIPTION OF CORNER 1/4 corner common to sections 27-34

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 12-22-69

WITNESSES TO CORNER.....



7" R. Pine S 22 W 12.0'

8" R. Pine N 78 E 9.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored by proportionate measurement, midpoint on line between sectbn corners during a survey in this township. No original evidence. Schaaf pipe removed.

SURVEYOR'S SEAL

SIGNED *Keith Ostling* DATE 12-29-69
REGISTERED LAND SURVEYOR #10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68