

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY  
T 28 N R 2 E

DESCRIPTION OF CORNER Section corner common to Sections 14-15-22-23

CORNER MONUMENT Left 1½" pipe in place in road

DATE MONUMENT PLACED AND WITNESSED 12-22-69

WITNESSES TO CORNER.....



7" Oak S 64 W 35.5'

7" W. Pine N 60 W 46.7'

AND

10" W. Pine N 35 E 44.7'

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement in this township. Corner was established in early 1900s survey by C. O. Seeley and used for control in various subsequent surveys. Considerable occupation now tied to this location.

SURVEYOR'S SEAL

SIGNED County Estling DATE 12-29-69  
REGISTERED LAND SURVEYOR #10068

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing