

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY  
T 28 N R 2 E

DESCRIPTION OF CORNER 1/4 corner common to Sections 15 - 22

CORNER MONUMENT Left 1 1/2" pipe in place

DATE MONUMENT PLACED AND WITNESSED 12-23-69

WITNESSES TO CORNER.....



14" B. Oak S 55 E 31.4'

14" B. Oak N 45 E 25.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey in this township. Found 1 1/2" pipe in road, as established in early 1900 survey by C. O. Seeley, and used in subsequent surveys. Corner of long standing, and some occupation based on this position.

SURVEYOR'S SEAL

SIGNED

*Keith J. Estlin*  
REGISTERED LAND SURVEYOR #10068

DATE

12-29-69

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68