

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

OSCODA COUNTY


T 28 N R 2 E

DESCRIPTION OF CORNER 1/4 corner on S. Side of Sec. 34

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 12-22-69

WITNESSES TO CORNER.....



12" Tw. W. Pine S 56 E 19.3'

11" W. Pine N 09 E 65.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored by proportionate measurement, midpoint on line between section corners. Unable to locate any previous corner.

SURVEYOR'S SEAL

SIGNED

*Kenneth H. Estling*

DATE

12-29-69

DISTRIBUTION:

REGISTERED LAND SURVEYOR #10068

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68