

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 E

DESCRIPTION OF CORNER 1/4 Corner Common to Sections 23 - 26

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 12-23-69

WITNESSES TO CORNER..... 8" R. Pine S 74 W 97.6'



8" W. Pine N 75 E 79.5'

* R. Pine Stp N 05 E 18.0'

AND * Beeley NBT

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement in this area. Found Seeley stake bottom from his NBT of record, as established in early 1900 survey. Considered best available evidence.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED *Kenneth J. Ostberg* DATE 12-29-69
REGISTERED LAND SURVEYOR #10068

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68