

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 E

DESCRIPTION OF CORNER Sec. corner common to Sections 22-23-26-27

CORNER MONUMENT Set Dept. Mon.

DATE MONUMENT PLACED AND WITNESSED 12-23-69

WITNESSES TO CORNER..... 7" Oak S 43 W 13.2'



1" W. Pine S 68 W 10.9'

4" W. Pine S 61 E 48.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored during a retracement in this township. Set corner on line and double distance over 1/4 and sections corner East, as called for in C. O. Seeley record of survey. Seeley apparently found a corner here, but took no witnesses. Consider this the best restoration available.

SURVEYOR'S SEAL

SIGNED *Annita J. Wetling* DATE 12-29-69
REGISTERED LAND SURVEYOR #10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing