

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 E

DESCRIPTION OF CORNER E 1/16 corner common to Sections 29-32

CORNER MONUMENT Set 1 1/2" x 18" pipe

DATE MONUMENT PLACED AND WITNESSED 6-3-70

WITNESSES TO CORNER.....



BT 5" J. Pine N 80 W 29.5

BT 5" J. Pine S 29 E 6.1

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by survey procedure during a retracement in this township.
Set to mark State boundary.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED *Walter H. Heston* DATE 7-7-70
REGISTERED LAND SURVEYOR 10068

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68