

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

OSCODA COUNTY

T 28 N R 2 E


T 28 N R 3 E

DESCRIPTION OF CORNER N 1/16 Corner common to Sections 25 - 30

CORNER MONUMENT Set 1"x36" pipe only

DATE MONUMENT PLACED AND WITNESSED 6-3-70

WITNESSES TO CORNER..... 9" R. Oak N 59 E 20.3



5" S. Maple N 72 W 23.5

Edge of Pond South 44'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by survey procedure during a retracement in this township.
Set to mark State ownership boundary.

SURVEYOR'S SEAL

SIGNED *Ernest Dettling* DATE 7-7-70
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68