

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 E
T 28 N R 3 E

DESCRIPTION OF CORNER 1/4 corner common to Sections 25 - 30

CORNER MONUMENT Set Dept Monument below surface

DATE MONUMENT PLACED AND WITNESSED 6-3-70

WITNESSES TO CORNER.....



12" Bl Oak N 79 W 103.5

12" R. Pine N 11 E 222.7

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored by proportionate measurement during a survey in this township. Could not locate anything for a previous corner in road fill. Falls about 8' East of apparent center of N-S County road.

SURVEYOR'S SEAL

SIGNED *Kenneth Ositing* DATE 7-7-70
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68