

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

OSCODA COUNTY


T 28 N R 2 E
T 27 N R 2 E

DESCRIPTION OF CORNER Sec. Corner common to Sections 35-36-1-2-

CORNER MONUMENT Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 6-3-70

WITNESSES TO CORNER.....



8" Maple N 42 W 46.4'

7" Maple N 05 E 100.00'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered during a survey in this township. Found corner as established by M. Schaaf in 1934 survey. Appears to have been locally accepted. Used in Road alignment and ROW determinations.

SURVEYOR'S SEAL

SIGNED *Kenneth D. Ostling* DATE 7-7-70
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68