

Duplicate (cont)

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


	OSCODA		COUNTY	
T	28	N	R	2 E
T	27	N	R	2 E

DESCRIPTION OF CORNER 1/4 corner common to Sections 36-1

CORNER MONUMENT Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 6-3-70

WITNESSES TO CORNER..... _____



3" R. Pine S 24 W 24.7'

3" r. Pine S 33 E 60.0'

AND _____

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement of this township. Found Schaaf pipe at corner, as established in 1934 survey. Used recently by County Surveyor for road alignment and R.O.W. determinations. Best available evidence.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Pettig* DATE 7-7-70
 REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse
 Area Forester (Regions I & II)
 District or Region Surveyor
 Forestry Div., Lansing